



# Release Note

## Univerge SV8100 TSP 9.0.2

**FCO 2013.041**

Issue 1

**System** : Univerge SV8100  
**Date** : 30<sup>th</sup> April 2013  
**Change Decision** :  
**Category** : Maintenance  
**Product Identity** : v9.0.2  
**Necessary Material** :

Material	12 NC

*Queries concerning this document can be addressed to <mailto:NecTechSupp@neci.co.uk>*

**Author** : Andy Smedley

FCO 2013.041

1 - 4

## TABLE OF CONTENTS

<b>1</b>	<b>IDENTIFICATION</b> .....	<b>3</b>
<b>2</b>	<b>ASSOCIATED PRODUCTS</b> .....	<b>3</b>
<b>3</b>	<b>COMPATIBILITY</b> .....	<b>3</b>
<b>4</b>	<b>UPGRADE INSTRUCTIONS</b> .....	<b>3</b>
<b>5</b>	<b>FUNCTIONAL CHANGES</b> .....	<b>3</b>
<b>6</b>	<b>KNOWN PROBLEMS</b> .....	<b>3</b>
6.1	List of Solved Problems .....	3
6.2	Description of Solved Problems .....	3
<b>7</b>	<b>MATERIALS</b> .....	<b>4</b>
7.1	Physical Distribution .....	4
7.2	On-line Information.....	4
<b>8</b>	<b>HISTORY</b> .....	<b>4</b>

## 1 IDENTIFICATION

This FCO provides information about the 9.0.2 Release of Univerge SV8100 TSP Software. This relates to the following items :-

SV8100

## 2 ASSOCIATED PRODUCTS

None

## 3 COMPATIBILITY

It is recommended that SV8100 R8.0 or above is used to run TSP R9.0.2

## 4 UPGRADE INSTRUCTIONS

Run relevant setup.exe (32 or 64bit 1<sup>st</sup> or 3<sup>rd</sup> Party) as would for normal install.

## 5 FUNCTIONAL CHANGES

## 6 KNOWN PROBLEMS

N/A

### 6.1 List of Solved Problems

The following externally reported problems are solved with the SV8100 upgrade:

Reference	Sales Channel
-	All

### 6.2 Description of Solved Problems

Reference	Description
-	TSP resynchronization issue (CPU 8.x and TSP 8.0.1).

## **7 MATERIALS**

### **7.1 Physical Distribution**

N/A

### **7.2 On-line Information**

The Release Note (FCO) and applicable software can be downloaded from the software database on BusinessNet.

BusinessNet URL : <http://businessnet.nec-unified.com>.

## **8 HISTORY**

20<sup>th</sup> February 2013 – Issue 1